

## S-430AC Auto Lead Cutter Machine



## description:

Used for hand-held program design, parameter modification, and equipment status monitoring. After programming or modifying parameters, the handheld box can also be used for other devices of the same model. However, it must be plugged in or unplugged only when the power is off, otherwise the handheld box will be damaged.

Handheld Box

After cutting and cutting the pins, it is sucked into the collection cup in real time and rotated to remove it for easy cleaning.

Scrap Lead  
collection cup

Operation panel

Used to connect equipment air source interface

switch

Handheld Box Interface

Z axis

Control the scissors up and down

X axis

X axis controls scissors to move left and right

Adjustable scissors cutting angle and blade  
centering position

Scissors set

Precision fixture


For clamping different PCBA products to be  
processed, the width can be easily adjusted at will

Y axis

Control precision clamp belt to move back and forth with  
PCBA board



## description:



# S-430AC Auto Lead Cutter Machine

- Current Status: Cutting Lead By Manual
- PCBA Samples & Component need to be cutted
- Our Solution: S-430AC Auto Lead Cutter Machine




## S-430AC Advantages:

- Save labor cost, avoid difficult recruitment situations.
- Improve productivity and shorten the production cycle.
- Speed: 7200 CPH
- Full Automatic
- Easy Operation. No experience request for operators.
- Self-Developed Software. Simple programming.
- Excellent lead cutting accuracy by Special designed Four-axis lead cutting card.
- Pliers head can be adjusted at any angle and direction
- The machine automatically calculates the compensation point, and only needs to specify the supplementary distance between the plane and the space, the computer can calculate the position of the compensation point.
- Orbital universal fixture, more convenient and fast when changing the wire, no need to open another clamp for different products

## S-430AC Machine Specification

- Speed: 7200 CPH
- Machine Dimension (L\*W\*H):720\* 720\* 900
- Cutter Clinch Direction: X axis 400mm \* Y axis 280mm \* Z axis 100mm \* R axis 360° rotation \* U axis (manual) 90 °
- PCB Size: Min.20mm\* 50mm Max. 200mm\* 360mm . (Optional 280mm\* 380mm)
- PCBA Height: Max110mm. Optional for other size.
- Direction: L to R (R to L)
- Machine Weight :100KG
- Power Supply: 220V/1.5KW (Energy saving)
- Type of pliers: Special pliers for Pneumatic machine
- MES system: connect production lines to achieve data management (optional)
- Extraction part pin method: vacuum aspiration
- Shearing capacity: copper wire  $\phi$  3.0mm or less  
(Change different cutting pliers for different wire diameters)

## S-430AC Requirements for PCB





The leads cannot be bent too far, The distance is better than 2mm, to facilitate machine cutting efficiency



Requires PCB have a process edges, to fix the PCB and facilitate machine operation


- Component Lead Cut by manually?
- High Labor cost?
- Quality issue?



## Using the machine to replace their manual work



## Video presentation:



Low speed:3000 CPH, small scissors head



Medium speed:5000 CPH, large scissor head

# Welcome inquiry

- 1, Please visit : [www.smthelp.com](http://www.smthelp.com)
- 2, Find us more: <https://www.facebook.com/autoinsertion>
- 3, Know more our team: <https://cn.linkedin.com/in/smtsupplier>
- 4, Welcome to our factory in Shenzhen China
- 5, Google: Auto+Insertion
- 6, See machine working video: youtube - Auto Insertion
- 7, Looking forward to your email: [info@smthelp.com](mailto:info@smthelp.com)